



No. 1 Workshop, M-10, Middle section, Science & Technology Park,  
Shenzhen, Guangdong, China 518057  
Telephone: +86 (0) 755 2601 2053  
Fax: +86 (0) 755 2671 0594  
Email: ee.shenzhen@sgs.com

## VERIFICATION OF RED COMPLIANCE

Verification No.: SZEM1905014147CRV01  
Product Description: Door/window sensor, Water Leakage sensor, Temperature sensor  
Model No.: Please refer to page 2  
Applicant: NGSTB Company Limited  
Address of Applicant: ROOM 702 KOWLOON BUILDING 555 NATHAN ROAD KL,  
HongKong  
Test Report Number(s): SZEM190501414701, SZEM190501414702,  
SZEM190501414703, SZES181100566101.  
Standards Required: EN 301 489-1 V2.1.1, EN 301 489-17 V3.1.1,  
EN 300 328 V2.1.1, EN 62479:2010,  
EN 60950-1:2006+ A11: 2009 + A1: 2010 + A12: 2011 + A2: 2013.

### Conclusion

Based on a review of the test report(s) detailed above, this apparatus meets the requirements of above standards. The product is in conformity with the essential requirements of Article 3.1 (a) the protection of the health, property and safety, 3.1 (b) an adequate level of electromagnetic compatibility and 3.2 effective use of the spectrum of 2014/53/EU.

The CE mark as shown below can be used, under the responsibility of the manufacturer, after completion of an EU Declaration of Conformity and compliance with all relevant EU Directives.

Keny Xu

EMC Laboratory Manager



Date: 2019-09-03



SGS-CSTC Standards Technical Services Co., Ltd.  
Shenzhen Branch, EMC Laboratory.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.  
Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

No.1 Workshop, M-10, Middle Section, Science & Technology Park, Shenzhen, China 518057 t (86-755) 26012053 f (86-755) 26710594 www.sgs.com.cn  
中国·深圳·科技园中区M-10栋一号厂房 邮编: 518057 t (86-755) 26012053 f (86-755) 26710594 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Model No.: NG01, NG01.01, NG01.02, NG01.03, NG01.04, NG01.05, NG01.06, NG01.07, NG01.08, NG01.09, NG01.10, NG01.11, NG01.12, NG01.13, NG01.14, NG01.15, NG01.16, NG01.17, NG01.18, NG01.19, NG01.20, NG02, NG02.01, NG02.02, NG02.03, NG02.04, NG02.05, NG02.06, NG02.07, NG02.08, NG02.09, NG02.10, NG02.11, NG02.12, NG02.13, NG02.14, NG02.15, NG02.16, NG02.17, NG02.18, NG02.19, NG02.20, NG03, NG03.01, NG03.02, NG03.03, NG03.04, NG03.05, NG03.06, NG03.07, NG03.08, NG03.09, NG03.10, NG03.11, NG03.12, NG03.13, NG03.14, NG03.15, NG03.16, NG03.17, NG03.18, NG03.19, NG03.20